

MILWAUKEE CITY HALL HISTORIC BUILDING RESTORATION PROJECT




**A Pictorial
Progress Report
to the Public
Works Committee
February 14, 2007**

Construction Progress to Date


- Terra cotta, brick, and mock-up approvals
- Masonry cleaning approximately 100% complete
- Deconstruction / Construction of South Tower
- Dormer Construction – ongoing
- 12th floor Reconstruction
- Demolition of brick columns on the 12th floor south tower
- Demolition and removal of Slate Roofing





Installing 12th Floor Structural Steel




Replacement of Deteriorated Roof Beam in South Tower



Reforming Back-up Brick to Install New Terra Cotta on Gables



Slate Roofing Removal




Dormer Reconstruction



Dormer Reconstruction







Three Month Look Ahead

- Terra cotta, brick, and mock-up approvals
- Steel at the South Tower – On Going
- Pouring of The Ring Beam
- 8th floor Gutters Installation
- Dormer Construction - ongoing
- Pour new 12th floor slab
- Demolition of brick columns on the 12th floor south tower
- Decorative Copper Fabrication

